

OXCART

WE REQUIRE ANALYSIS OF FUEL SAMPLE

FROM IMPOUNDED TANK TRUCK WHICH SERVICED ARTICLE 926/123.

PLEASE ADVISE WHAT SIZE SAMPLE AND WHERE IT SHOULD BE SENT.

PARTICULARLY INTERESTED IN DISSOLVED WATER CONTENT. HYDRO KIT

CHECK PRIOR FUELING INDICATED LESS THAN 30 PPM, BUT DESIRE

FURTHER ANALYSIS OF THIS AND ALL FUEL PROPERTIES. SAMPLES PROBABLY

ALSO WILL BE SENT TO WRIGHT PATTERSON FIELD FOR ANALYSIS.

2. IF FUEL SYSTEM ICING WERE TO OCCUR IN ENGINE SYSTEMS WHAT WOULD WE EXPECT IN WAY OF SYMPTOMS OF HOLLEY R-95. WHAT WOULD WE EXPECT TO SEE ON R.P.M., E.G.T., FUEL FLOW, AND THRUST. THIS SHOULD BE WORKED OUT FOR THE FOLLOWING CONDITIONS:

	•	*		
ALT	MN	KEAS	PLA	
34 M	. 85	100 CD 100 TO	X	
38 M	1.05	100 day day day	X	
38M (EST)	***	DECREASING	Y (SLIGHT RETARD)	F
NOTE:	AT THIS	POINT, DRIVER IN	Y (SLIGHT RETARD)	

SECRET

GROUP !
Enderlad from automatic
downspecting and
declaratication

25X1A

Approved For Release 2000/05/05 : CIA-RDP71B00590R000200030027-3

9687(IN 77818) SECRET PAGE TWO

25X1A

.P. M. AND 1800 PPH FUEL FLOW.

- 5 TO 30M 160 TO 101 Z (POSSIBLE ADV) NOTE: Z SHOULD BE P.L.A. AT IMPACT.
- ALSO PLEASE COMMENT ON WHAT WOULD HAPPEN IF EMERGENCY FUEL STEM WERE SELECTED.
- 3. WE NEED SAME INFO AS ABOVE ASSUMING ENGINE AIR INLET SING WAS ENCOUNTERED.
- WHAT WOULD BE EFFECT OF OPERATION IN INVERTED ATTITUDE R ----- MINUTES. OF PARTICULAR INTEREST IS OIL SYSTEM D EXPECTED CONDITION OF BEARINGS.
- BOTH A/B NOZZLES APPEAR TO BE OPEN. WE SUSPECT INERTIA AT IPACT CAUSED THEM TO OPEN. DO YOU CONCUR THAT INERTIA COULD SULT IN A/B NOZZLE OPENING. ACTUATOR RODS APPEAR TO BE RANDOM EXTENSIONS. SOME FULL OPEN AND SOME INTERMEDIATE. ME ALSO APPEAR TO HAVE BEEN BENT WHILE IN NOZZLE CLOSED SITION.
 - 6. REGARDING ITEMS 2 AND 4. BLANKS WILL BE FILLED IN LATER SOON AS INFO IS AVAILABLE.

END OF MESSAGE